

CAS Product Quick Guide

CL-3000

CAS CL-3000- Label Printing Scale

Labelling Operation

Weight items

4. Press speed key to call up a PLU
OR
press PLU number + **PLU** key
5. Place item on the Platter.
6. Press **Print** Key to print a label.

Count items

4. Press speed key to call up a PLU
OR
press PLU number + **PLU** key
5. Enter the number of pieces
6. Press **Print** Key to print a label.

