

CAS Product Quick Guide

CN1

CAS CN1 - Label Printing Scale

Labelling Operation

Weight items

7. Press speed key to call up a PLU
OR
press PLU number + **PLU** key
8. Place item on the Platter.
9. Press **Print** Key to print a label.



Count items

7. Press speed key to call up a PLU
OR
press PLU number + **PLU** key
8. Enter the number of pieces
9. Press **Print** Key to print a label.